



San Francisco Bay Regional Water Quality Control Board

August 6, 2020
File No. SL0607548721 (jdw)

Presidio Trust
Attn. Ms. Nina Larssen
Remediation Program Manager
103 Montgomery Street
P.O. Box 29052
San Francisco, CA 94129-0052
Via email: nlarssen@presidiotrust.gov

Subject: **Water Board Review of June 22, 2020, *Revised Operations, Monitoring, and Maintenance Plan, Vapor Mitigation System and Cap* Riley Avenue Site, Buildings 127A, 127B, and 128A Fuel Distribution System, Section BR11-1 Presidio of San Francisco, San Francisco, California**

Dear Ms. Larssen:

I reviewed the Presidio Trust's June 22, 2020, *Revised Operations, Monitoring, and Maintenance Plan* (Revised OMMP) for the subject Site. The Revised OMMP describes the protocols for conducting operation, monitoring, and maintenance of the installed Vapor Mitigation System at Building 127B, and the concrete basements and surrounding exterior hardscape and landscape around Buildings 127A, 127B, and 128A. Based on my review, I concur with the Revised OMMP.

If you have any questions, please contact me at jeff.white@waterboards.ca.gov.

Sincerely,

Jeffrey D. White
Water Resource Control Engineer